



TURBOCHARGER MAINTENANCE GUIDE

Make	Model	Dismantle and Inspect (Hrs)	Overhaul (Hrs)	Overhaul (Yrs)
ABB	TPS44, TPS48, TPS52, TPS57, TPS61, VTR161, VTR201, VTR251, VTR304, VTR401, VTR454 & VTR500	8,000	12,000	5
	VTR214, TPL76, TPS48, TPS65, TPS67 & VTC254	8,000	16,000	5
	TPL65 & TPL71	8,000	35,000	5
	RR151	10,000	24,000	5
	VTR250		6,000	5
Holset	VTR254, VTR320, VTR321 & VTR354		8,000	5
	HX32, HX35, HX38 & HX40		10,000	5
	6" Series		12,000	5
Napier	SA084, SA085 & SA105		8,000	5
	HP100, HP200 & HP210		6,000	6
	NA295		8,000	5
	NA297, NA355, NA357, NA455 & NA457	8,000	24,000	5
MAN	NR15, NR20, NR24, NR29 & NR34		12,000	5
	NA48, NA57 & NA70		12,000 (24,000 for two-stroke engines)	5

If you have an upcoming turbo overhaul, we can provide a quotation.

Call our experts now on **+44 1206 791552**.

This is a guide only. The timings will depend on turbo specification, application and usage.